

Arbors for BDS core drills

Three systems are available – they allow a friction-type, convenient and secure connection between the core drill and the magnetic core drilling machine.

ACCOMMODATING OF EVERY DRILL

Arbors for
BDS core drills with
19 mm ($\frac{3}{4}$ ") Weldon shank



**KEYLESS quick-change
drilling system**

ORDER NO.	SPINDLE ARBOR
ZSS 200	MT 2
ZSS 300	MT 3

With automatic internal lubrication

for core drills with 19 mm ($\frac{3}{4}$ ") Weldon shank.

With tube and quick-lock coupling. Quick tool
change without wrench.



Reducing bush DIN 2185

ORDER NO.	EXTERNAL	INTERNAL
ZRH 210	MT 2	MT 1
ZRH 320	MT 3	MT 2
ZRH 430	MT 4	MT 3

Arbors for
BDS core drills with
19 mm ($\frac{3}{4}$ ") and
32 mm ($1\frac{1}{4}$ ") Weldon shank



**Industrial arbor
with manual internal lubrication**

ORDER NO.	SPINDLE ARBOR
For core drills with 19 mm ($\frac{3}{4}$ ") Weldon shank	
ZIA 219-M	MT 2
ZIA 319-M	MT 3
ZIA 419-M	MT 4
For core drills with	
32 mm ($1\frac{1}{4}$ ") Weldon shank	
ZIA 332-M	MT 3
ZIA 432-M	MT 4



Extension sleeve DIN 2178

ORDER NO.	EXTERNAL	INTERNAL
ZVH 220	MT 2	MT 2
ZVH 230	MT 2	MT 3
ZVH 320	MT 3	MT 2
ZVH 330	MT 3	MT 3

Arbors for
BDS core drills with
19 mm ($\frac{3}{4}$ ") and
32 mm ($1\frac{1}{4}$ ") Weldon shank



**Industrial arbor
with automatic internal lubrication**

ORDER NO.	SPINDLE ARBOR
For core drills with 19 mm ($\frac{3}{4}$ ") Weldon shank	
ZIA 219-KN	MT 2
ZIA 319-KN	MT 3
ZIA 419-KN	MT 4
For core drills with 32 mm ($1\frac{1}{4}$ ")	
Weldon shank	
With tube and quick-lock coupling.	
ZIA 332-KN	MT 3
ZIA 432-KN	MT 4